


How Pressure^x[®] is Used



Rotary Heat Sealer

- 1 Place a sheet of Pressure^x[®] pressure indicating film directly in between the clamping elements of your sealing platens.




Place Pressure^x[®] tactile surface sensors here ●


- 2 Instantaneously and permanently the film captures both the pressure distribution and magnitude that occurs between the contacting surfaces.




- 3 Final analysis: a "pressure map"



Color Indicates Precise PSI Value



Zoomed View



Pressure Profile