

APPLICATION: CONNECTOR INTERFACE ANALYSIS

- 1 Place a sheet of Fujifilm Prescale® film directly in your connector interface.
- 2 Instantaneously and permanently the film captures both pressure distribution and magnitude.
- 3 Final analysis: a pseudo colored “pressure map.”

