


SPC Method for Ensuring Optimal Junction Box Sealing Uniformity


Junction Box

1 Prior to applying adhesive, cut and position a piece of Fujifilm Prescale® on the bottom of the junction box and apply force.






Place Fujifilm Prescale® tactile surface sensor here

2 Instantaneously and permanently the film captures both the pressure distribution and magnitude that occurs between the contacting surfaces.



3 Final analysis: a "pressure map"



Zoomed View

Pressure Profile

